



POOL REFURBISHMENT WORK - Removal of damaged stone from existing overflow drain, construction of frame stage for keeping overflow gratings, fixing of new gratings, Epoxy painting for mushroom umbrella & its stage, fabrication work of railings & its painting, Acid wash, removal of damaged tiles, re-fixing of new tiles, grouting work & LED light fixing



Condition before commencing work...



Condition Before commencing work...





Civil work of Stage frame construction in overflow drain for keeping/fixing Gratings





GRATINGS FIXING WORK








GRATINGS ALIGNMENT THRU CUTTING & FIXING WORK









RAILINGS BEFORE & AFTER PAINTING & FABRICATION WORK





MASHROOM UMBRELLA BEFORE & AFTER EPOXY PAINTING







SWIMMING POOL ACID WASH & CLEANING WORK



MASHROOM UMBRELLA EPOXY PAINTING WORK








FINAL LOOK OF POOL AFTER WORK COMPLETION WITH NEW SLIDER & MUSHROOM UMBRELLA





FINAL LOOK OF POOL AFTER WORK COMPLETION WITH NEW SLIDER





PREEMIYAR POOLS PVT LTD

best pool for better swimming ...

For more information, please contact:

BENGALURU H.O.

MYSORE

HASSAN/COORG/CHIKMAGALUR

Preemiyar Pools Pvt Ltd. # 593, Nesara, 2nd Floor, 2nd Main, Opp H.M.V School, Annapoorneshwarinagar, Bengaluru - 560 091, India Ph: +91- 94484 - 56552

Preemiyar Pools Pvt Ltd. # 495, Mathrushree, 'G' Block. Ramakrishnanagar, Mysore - 570 006, India Ph: +91-636463 - 1155 Preemiyar Pools Pvt Ltd, Shrungari Nilaya, Near MKS Lions School. Fort, Konanur - 573 130, Hassan Dist, India Ph: +91-94484-60658

www.preemiyarpools.com | preemiyarpools@gmail.com

