





Replacement of Multiport Valve

Removal of Existing Old Media




Replacing Lateral Diffuser Nozzles

Fixing New Lateral Diffuser Nozzles



Fixing of New Pump

Installation of New Pump



Application of Materials to avoid Leakage

Fixing New Filter



Plumbing work for New Filter



Plumbing work for New Filter



Fixing of valves for plumbing Line



Final view of New Filter Setup



Filling water to pool

Final view of Pool





PREEMIYAR POOLS PVT LTD

best pool for better swimming ...

For more information, please contact:

BENGALURU H.O.

MYSORE

HASSAN/COORG/CHIKMAGALUR

Preemiyar Pools Pvt Ltd. # 593, Nesara, 2nd Floor, 2nd Main, Opp H.M.V School, Annapoorneshwarinagar, Bengaluru - 560 091, India Ph: +91- 94484 - 56552

Preemiyar Pools Pvt Ltd. # 495, Mathrushree, 'G' Block. Ramakrishnanagar, Mysore - 570 006, India Ph: +91-636463 - 1155 Preemiyar Pools Pvt Ltd, Shrungari Nilaya, Near MKS Lions School. Fort, Konanur - 573 130, Hassan Dist, India Ph: +91-94484-60658

www.preemiyarpools.com | preemiyarpools@gmail.com

